

Oil Field Environmental Incident Summary

Incident: 20140112002712 **Date/Time of Notice:** 01/12/2014 00:01

Responsible Party: Bosque Disposal Systems, LLC

Well Operator: BOSQUE DISPOSAL SYSTEMS, LLC

Well Name: JESSICA SWD 1

Field Name: BLUE BUTTES

Well File #: 90243

Date Incident: 1/11/2014 **Time Incident:** 19:30

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 23

Qtr:

Location Description:

Submitted By: Kendra Rossow

Received By:

Contact Person: Kendra Rossow
420 Throckmorton, Suite 640
Ft Worth, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Miles

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	600	barrels	600	barrels	600	barrels
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

None

Inspected:

Written Report Received: 1/16/2017

Clean Up Concluded: 1/13/2014

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

None

Action Taken or Planned:

Spill was contained within the berm area around tanks. Tank was isolated. Saltwater is being recovered by trucks.

Wastes Disposal Location: Jessica Saltwater Disposal (Onsite)

Agencies Involved:

Updates

Date: 1/13/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from tank leak, remained on SWD location within the tank diking, according to the report. NDIC retains oversight.